

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

Este informe contiene información muy importante sobre su agua potable.
Por favor hable con alguien que lo pueda traducir.

1,2,3-Trichloropropane Monitoring Requirements Not Met for AI Tahoe-STMS Water System During 2nd Quarter 2018

Our water system recently failed to sample for a required chemical during the 2nd Quarter 2018 and, therefore was in violation of the regulations. Although this is not an emergency, as our customers, you have a right to know what happened, what you should do, and what we did to correct the situation.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During the 2nd Quarter 2018, we did not collect a 1,2,3-trichloropropane (1,2,3-TCP) sample from our Well as listed in the table below and therefore, cannot be sure of the quality of our drinking water during that time.

What should You do?

- There is nothing you need to do at this time.
- The table below lists the contaminant we did not properly test for during the calendar year 2018, how many samples we are required to take and how often, how many samples we took, when samples should have been taken, and the date on which follow-up samples were taken.

Contaminant	Required sampling frequency	Number of samples taken	When all samples should have been taken	When samples were taken
1,2,3-TCP	4 quarterly samples during the 2018 calendar year from our Well	1 sample was taken in 1 st quarter and 1 sample was taken in 3 rd quarter	2 nd quarter sample was due by June 30, 2018	A sample was taken 1 st quarter on March 12, 2018 and a sample was taken 3 rd quarter on September 25, 2018

- If you have health issues concerning the consumption of this water, you may wish to consult your doctor.

What happened? What is being done?

We took the first quarter sample on March 12, 2018, and we forgot to take a second quarter sample. The first quarter sample had no detection of the 1,2,3-TCP contaminant. We were required to take a second quarter water sample to test for this contaminant by June 30, 2018 and this was not taken. We took a 3rd quarter sample on September 25, 2018 and it showed <0.005 ppb (parts per billion). We plan to take the remaining 1,2,3- TCP quarterly samples as follows: by December 31, 2018, and by March 31, 2019.

We are in process of consolidation with South Tahoe Public Utility District (STPUD) and are hoping that this will happen during the Spring of 2019. We are still required to complete all of our water quality monitoring until we complete the consolidation project.

For more information, please contact:

Water System Contact Name: Billy Wessell, Chief Business & Operations Officer

Phone Number (530) 541-2850

Mailing Address: 1021 AI Tahoe Blvd, South Lake Tahoe, CA 96150